



| Position | Amount | Type number | Description | PG |
|----------|--------|-------------|-----------------------------------|----|
| 1 | 1 | 314000540 | Handle cpl. | 22 |
| 2 | 1 | 316040610 | Spindle stop compl. | 14 |
| 3 | 1 | 316049660 | Gear housing compl. | 29 |
| 4 | 1 | 341100940 | Hexagon nut w.recess | 12 |
| 5 | 1 | 316049650 | Bevel gear and pinion | 27 |
| 6 | 2 | 141110460 | Fillister head screw | 11 |
| 7 | 1 | 143115420 | Ball bearing, 8x22x7 | 18 |
| 8 | 1 | 339135750 | cover plate | 11 |
| 9 | 1 | 343392740 | Sealing washer | 16 |
| 10 | 1 | 143115870 | Ball bearing, 6x19x6 | 15 |
| 11 | 1 | 310010370 | Armature compl.,230V | 40 |
| 12 | 1 | 344095260 | Rubber bushing | 12 |
| 13 | 1 | 343430250 | Baffle | 11 |
| 14 | 1 | 343430240 | Motor cap | 16 |
| 15 | 6 | 141116020 | Self-tap fill h screw | 12 |
| 16 | 1 | 344097550 | O-ring 48 x 1 | 11 |
| 17 | 1 | 341161150 | Spindle M14 | 19 |
| 18 | 1 | 143192540 | O-ring | 11 |
| 19 | 1 | 341032160 | Flange compl. | 31 |
| 20 | 4 | 141120070 | Fill. head screw | 11 |
| 21 | 1 | 341106900 | Flange nut | 20 |
| 22 | 1 | 341031160 | Clamping flange | 22 |
| 23 | 1 | 339209420 | Wheel guard compl.,Ø125 | 26 |
| 24 | 1 | 338122160 | M-Label,08 52x22 | 11 |
| 25 | 1 | 343411150 | Switch slide | 11 |
| 26 | 1 | 343430220 | Switch rod | 11 |
| 27 | 1 | 343362490 | Cable clip | 12 |
| 28 | 1 | 311011530 | Field coil compl.,230V | 32 |
| 29 | 1 | 338066000 | Rating plate, 01237000 W 1100-125 | 11 |
| 30 | 1 | 343430230 | Motor housing | 21 |
| 31 | 1 | 338122540 | Metabo plate | 11 |
| 32 | 1 | 343013000 | Carbon brush set | 20 |
| 34 | 2 | 343000870 | Brush holder | 14 |
| 35 | 1 | 343411110 | Switch,FPCe 230 V | 26 |
| 36 | 1 | 344097360 | Cable sleeve | 11 |
| 37 | 1 | 344499540 | Cable w.CEE plug | 23 |
| 38 | 1 | 344163920 | Pin spanner | 14 |
| 39 | 1 | 339007790 | Washer | 11 |
| 40 | 1 | 339060160 | Compensating Washer | 12 |
| 880 | 1 | 344130910 | Grease 100G | 24 |
| 1001 | 1 | 338504470 | Diagram | |

